

NATIONAL PARK SERVICE, WESTERN REGION
HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
CAL,
42-Lompoc
3-

San Antonio Creek Bridge
State Highway 1 *Lompoc Valley*
Santa Barbara County
California

HAER No. CA-18

Ed Andersen, Photographer May, 1982

- | | |
|----------|--|
| CA-18-1 | VIEW NORTH ALONG DECK CENTERLINE |
| CA-18-2 | VIEW SOUTH ALONG DECK CENTERLINE |
| CA-18-3 | VIEW EAST, DOWNSTREAM SIDE |
| CA-18-4 | VIEW WEST, UPSTREAM SIDE |
| CA-18-5 | VIEW NORTHWEST, UPSTREAM SIDE |
| CA-18-6 | VIEW NORTH, DETAIL, E.L. MAYBERRY PATENT ARCH-RIB FLOOR SYSTEM, UNDERSIDE OF DECK |
| CA-18-7 | VIEW EAST, DETAIL, E.L. MAYBERRY PATENT ARCH-RIB FLOOR SYSTEM, UNDERSIDE OF DECK |
| CA-18-8 | VIEW NORTH ALONG DECK CENTERLINE
File photo, Caltrans Office of Structures Maintenance, March, 1934. Photographer unknown. |
| CA-18-9 | VIEW NORTH ALONG DECK CENTERLINE
File photo, Caltrans Office of Structures Maintenance, July, 1956. Photographer unknown. |
| CA-18-10 | VIEW NORTH ALONG DECK CENTERLINE
File photo, Caltrans Office of Structures Maintenance, September 1968. Photographer unknown. |
| CA-18-11 | VIEW EAST, DOWNSTREAM SIDE
File photo, Caltrans Office of Structures Maintenance, February, 1934. Photographer unknown. |
| CA-18-12 | VIEW NORTHEAST, DOWNSTREAM SIDE
File photo, Caltrans Office of Structures Maintenance, September, 1968. Photographer unknown. |